Supplier Quality Collaborative Efforts for Problem Solving

Purpose

8-Disciplines of Problem Solving PDCA Model



D1- Define the Team



D2- Describe the Problem



D2- Describe the Problem



process. This is normally the toughest aspect of the problem solving
process: it
root causes of the problem were ob
toms, not root causes.
The second, the specific causes that allowed the
Flow Charts
Audits
FMEA

D4- Root Cause Analysis



D4- Root Cause Analysis

D6 – Verification of Corrective Action(s)

D7 – Preventive Action(s)

D8 – Congratulate the Team